

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/22/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 08/16/12 – 1200, 08/23/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Aerial Field Observer	Houston, TX	
8. Activity Log			
Time	Major Events		
	<p><b>Operational Observation:</b></p> <ul style="list-style-type: none"> <li>0730 Arrived at the ICP</li> <li>0800 Began the production of the Situational Photolog for the EPA C&amp;G.</li> <li>0800 Attended the EPA C&amp;G meeting.</li> <li>0900 Arrived at C0.4 Boat Launch and launched the boat.</li> <li>Observed spots of silver sheen around the C0.4 boat launch.</li> <li>MP5.0 – MP5.63 LDB observed tar globs and sheen.</li> <li>MP5.55 observed a poling crew operating.</li> <li>MP5.63 LDB observed a large area of silver sheen, Tar globs and rainbow sheen.</li> <li>Ceresco Dam observed the sheen sweep boat performing boom maintenance.</li> <li>MP5.7 – MP5.55 RDB observed silver sheen.</li> <li>MP4.75 observed second poling crew operating.</li> <li>MP4.5 below the former Island F observed sheen. The quantity of sheen observed did not warrant a sweep boat.</li> <li>10:30 Pulled the boat and relocated to C5 boat launch.</li> <li>MP14.25 LDB observed the third poling crew operating.</li> <li>MP15.5 South Mill Pond observed no sheen.</li> <li>11:30 Pulled the boat and returned to the ICP.</li> <li>13:30 Boarded the helicopter for the weekly overflight.</li> <li>Source Area and Talmadge Creek no sheen observed.</li> <li>Frac-City decontamination pad, no activity observed.</li> <li>MP5.0 poling crew observed.</li> <li>MP5.55 observed a poling crew operating.</li> <li>Ceresco Dam observed crew removing debris from the control point.</li> <li>MP5.63 LDB sheen observed.</li> <li>MP5.9 RDB sheen observed above the dam.</li> <li>MP7.5 observed a river bank erosion crew.</li> <li>MP10.75 no sheen observed.</li> <li>MP14.25 RDB observed a poling crew operating.</li> <li>MP15.5 South Mill Pond no sheen observed.</li> <li>MP21.5 Custer Drive Bridge no sheen observed.</li> <li>MP26.0 RDB no sheen observed.</li> <li>MP26.25 no sheen observed.</li> <li>MP30.8 no sheen was observed.</li> <li>Morrow Lake Delta observed a crew performing camera boom inspections along Boom A.</li> <li>Morrow Lake Delta observed a crew collecting debris from along Boom E.</li> <li>Morrow Lake Delta observed a water fountain in the southeast corner of the Delta.</li> <li>Morrow Lake southern cover observed the sweep boat operating.</li> <li>1500 Return to the ICP and began daily photo log.</li> </ul>		

	<b>Planning Activities:</b> <ul style="list-style-type: none"><li>• Completed 214</li><li>• Prepared and distributed Daily Situation Unit Photo Log.</li><li>• Began writing the SitRep.</li></ul>
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START